


## GWHD-21-NK600




Absicherung = 16 Ampere träge



# SCHALTPLAN

GWHD-21-NK600



## WARNING

Please don't touch any electronic component or terminal when the machine is running, stopping or has been powered off for less than 30 minutes to prevent the risk of electric shock!